



CN-FM

FLOW METER CONNECTOR

Solder the White or Brown (Signal) wire to Terminal A and the Ground (Black) wire to Terminal B as shown below.

